

Work in the Old Smithville Burying Grounds for October 2012

1. Lucy N stone at Northrop lot, Section BN, A-7: Base straighten, Stone adhered to base



2. Ewell Lot, Section BN, B-6: Fence added to from pieces of another broken fence, small stone set up vertical.

BEFORE



AFTER



3. Phelps family name stone, Section BN, A-6: Base lifted, big stone moved toward back.

BEFORE:



AFTER:



4. Bryan Morse stone, Section NR, E-4: Big white land mark marker made out of several stones. Tried to straighten it, but pedestal under is made out of bricks that are no longer cemented together. Was able to move the upper stones back from their edge. Was able to place some small pieces of wood under it, but it needs more work than I can give it.

BEFORE:



AFTER:



5. Peadrick Stones, Section BN, B-6: Fixed the Alice K one where it rocked back and forth (smaller one). Put stones under the larger stone to the left where the base had sunk and the stones on top were moving toward the ground.



6. Martha Hood stone, Section BM, E-7: Leading badly, big, and made of several smaller stones. Moved smaller stones away from the lower side. Tried to get under it, but foundation goes down to the crypt and I can't be certain that the jack I use will not go into the crypt. Need professional help.

BEFORE:



AFTER:



7. Mary Susan Potter –Section BM, F-8: Put stones under the base leveling it, put top obelisk back on base.

BEFORE:



AFTER:



8. Capt Andren Currick – Section BM, F-8: Straighten.



9. Price/Swan Lot – Section BN, G-6: Put stones under 5 bases, epoxied 2 bases, epoxied 5 different head stones. relocated 3 foot stones.

BEFORE:



AFTER::



10. Thomas G. Drew stone Section NR, F-3: Moved stones back toward the back to keep stone from falling forward.



11. Lousia Smith Doshier St. George stone Section NR, A-3: Epoxied head stone back together (Homework left from Eric Kozan school in May, 2009).



Work In Old Smithville Burying Grounds – November 2012

1. John Julius Doshier Stone – Quadrant BN Location G6 - Stone top broken off, base was not adhered to foundation so that grave stone tipped over. Cleaned where stones are to be joined together. Used SHS cemetery cement the first time to join bottom stone to foundation. It did not work. Clean foundation again. Used epoxy for the second time to get bottom stone to adhere to foundation. Had help from Scott and Robert Jones to get top piece in place. Epoxied top piece to bottom piece.

Before



After



2. Eliza Sellers Stone – Quadrant BN Location G6 – Grave Stone down on ground flat on back. Found foundation in ground. Cleaned both stone and foundation where joined together. Epoxied grave stone upright to foundation.

Before



After



3. Sellers' Twins stones – Little Buddie - Mary Ceicel - Quadrant BN, Location 16 – Grave stones down flat on ground. Base of grave stones broken and left in main foundation. Little Buddie stone was broke into 3 sections. Leveled foundation stones. Clean up the slot where the gravestone fits in. Cleaned where stones were to be joined together Epoxied the stones back into foundation and into 1 piece. Cleaned the stone's faces.

Before



After



4. Elizabeth Ruark stone – Quadrant BM, Location F7 – Grave stone down flat on ground, stone key left in foundation stone. Dug out the keystone. Leveled the foundation stone. Cleaned out the slot in foundation stone. Cleaned where stones are to be joined together. Epoxied the gravestone to the foundation stone twice. Cleaned the grave stone face.

Before



After



5. Ellen Clemmons Stone – Quadrant NR, Location F1 - Stone was leaning. Leveled stone using pebbles.

Before



After



6. Olie Watts stone – Quadrant BM, Location D6 - Foundation stone not level, Gravestone broken into 2 pieces. Leveled foundation stone using pebbles. Cleaned where stones are to be joined together. Epoxied lower stone to foundation. Epoxied the top of stone to lower stone. Joe Loughlin helped with placement of the top stone. Cleaned the stone face. Replaced Flowers (not in photos).

Before



After



7. Charles V. Fullwood – Quadrant BM, Location E5 Foundation stone not level, Stone broken into 2 sections. Leveled foundation stone using pebbles. Cleaned where stones are to be joined together. Epoxied lower stone to foundation. Epoxied the top of stone to base. Cleaned the stone face. Replaced flowers (not in photos)

Before



After

